Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	0	delubrification.ab.	USPAT	OR	OFF	2004/11/11 14:06
S2	1	delubrication.ab.	USPAT	OR	OFF	2004/11/11 13:14
S3	0	delubrification	USPAT	OR	OFF	2004/11/11 14:06
S4	60	lubrification	USPAT	OR	OFF	2004/11/11 14:08
S5	353	(432/121).CCLS.	USPAT	OR	OFF	2004/11/11 14:23
S6	24	burner and (convey\$ or belt\$2)and S5	USPAT '	OR	OFF	2004/11/11 15:16
S7	277	(432/128).CCLS.	USPAT	OR	OFF	2004/11/11 14:23
S8	32	burner and (convey\$ or belt\$2) and S7	USPAT	OR	OFF	2004/11/11 14:23
S9	32	S8 not S6	USPAT	OR	OFF	2004/11/11 14:34
S10	245	S7 not S9	USPAT	OR	OFF	2004/11/11 15:14
S11	1	("6241515").PN.	USPAT	OR	OFF	2004/11/11 15:15
S12	440	((432/130) or (432/133) or (432/136)).CCLS.	USPAT	OR	OFF	2004/11/11 15:15
S13	413	S12 not (S6 S7)	USPAT	OR	OFF	2004/11/11 15:15
S14	32	burner and (convey\$ or belt\$2) and S13	USPAT	OR	OFF	2004/11/11 15:29
S15	113	(432/143).CCLS.	USPAT	OR	OFF	2004/11/11 15:41
S16	186	(432/146).CCLS.	USPAT	OR	OFF	2004/11/11 16:04
S17	163873	(furnace oven) and delubricat\$ and (convey\$ belt\$3) exhaust	USPAT	OR	OFF	2004/11/11 16:05
S18	0	(furnace oven) and delubricat\$ and (convey\$ belt\$3) and exhaust\$2	USPAT	OR `	OFF	2004/11/11 16:05
S19	2638	(furnace oven) and (convey\$ belt\$3) and exhaust\$2 and burner	USPAT	OR	ON	2004/11/11 16:05
S20	308	\$sinter\$ and S19	USPAT	OR	ON	2004/11/11 16:06
S21	301	S20 not (S15 S16 S14 S10 S8)	USPAT	OR	ON	2004/11/11 16:08
S22	20	(remov\$5 with (coat\$4 lubric\$6)). ab. and S19	USPAT	OR	ON	2004/11/11 16:09
S23	3886	(remov\$ near7 coat\$5).ab.	USPAT	OR	OFF	2004/11/11 16:41
S24	2580	(furnace oven heat\$4) and S23	USPAT	OR	OFF	2004/11/11 16:42
S25	563	(convey\$ belt\$) and S24	USPAT	OR	OFF	2004/11/11 16:42